




Pozícia	Počet	Typové číslo	Označenie	PG
7	1	343432470	Gehaeuse m.Deckel	27
8	1	343394790	Schaltschieber	11
9	1	343394770	Druckstueck	11
10	1	342021670	VALCOVA PRUZINA	11
11	1	343433250	Schaltschieber,R/L	11
12	1	316051650	Schaltschieber vollst.	13
13	11	141113180	Sosovkovita skrutka	11
14	1	316051390	Getriebe vollst.,Quick	38
15	1	310011160	Anker vollst.,18 V	36
17	1	338059370	Typovy stitok	13
22	1	338129940	SYMBOLOVY STITOK	12
29	1	314001030	Zusatzhandgriff vollst.	23
30	1	314001340	Zusatzhandgriff vollst. (225 Nm)	45
31	1	339137270	Haken	13
32	1	343448690	BIT-PUZDRO	13
33	1	316052150	Vorsatz f. 100Nm LTX	44
35	1	338123790	SYMBOLOVY STITOK	11
36	1	338123360	Metabo-Schild patent pending	11
41	1	343083610	Stellrad vollst.	26
42	1	316053840	Schalter vollst. mit Kohlehalter	45
43	1	143160120	Ferritring	13
52	1	316049910	C/O-KRUZOK SADA	14
95	1	343439680	Abdeckkappe	11
850	1	627240000	Schnellwechselbohrfutter Futuro Plus S1M	
1001	1	338505830	SCHEMA ZAPOJENIA	

