



Position	Amount	Type number	Description	PG
1	1	316097440	Gear housing compl.	27
2	1	316040610	Spindle stop compl.	14
3	3	141120070	Fill. head screw	11
4	7	141123940	Self-tap. fill. h. screw	11
5	1	316097810	Flange compl.	29
6	1	339013130	Compensating Washer	11
7	1	316097550	Bevel gear and pinion	24
8	1	143195640	O-ring	11
9	1	341166770	Spindle	18
10	1	339007790	Washer	11
11	1	143193920	O-ring	18
12	1	341102660	Hex nut M7	11
13	1	143116270	Ball bearing, 8x22x 7	15
14	1	141156650	Retaining ring	11
15	1	339007940	Washer	11
16	1	339153550	Baffle	11
17	1	310012760	Armature compl., 110V	34
18	1	343392740	Sealing washer	16
19	1	143115870	Ball bearing, 6x19x6	15
20	1	344114190	Rubber bushing	11
21	1	339151290	Baffle	11
22	1	314000540	Handle cpl.	22
23	1	311012870	Field coil compl., 120V	29
24	1	343446520	Motor housing	20
25	1	338070240	Rating plate	13
26	1	316097610	Brush holder compl.	20
27	1	343013510	Carbon Brush 120V	19
28	1	343446510	Motor cap	15
29	1	141116020	Self-tap fill h screw	12
30	1	343362490	Cable clip	12
31	1	343446380	Cable sleeve	11
32	1	344492750	Cable with UL-CSA-plug	23
33	1	316097460	Shift lever compl.	18
34	1	338122160	M-Label, 08 52x22	11
35	1	343410280	Switch 2-pole	20
36	1	338122090	Warning Label 52x22	11
37	1	339204500	Wheel guard, D125	20
39	1	341031290	Clamping flange	19
40	1	341101480	Flange nut	20
41	1	344163920	Pin spanner	14
42	1	342022040	Spring clip	11

Position	Amount	Type number	Description	PG
43	1	316066040	Clamping lever compl.	22
880	1	344130910	Grease 100G	24
1001	1	338504470	Diagram	

